

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

ALLIANCE AEROSPACE ENGINEERING, LLC.
185 PAULARINO AVE. SUITE A
COSTA MESA, CALIFORNIA 92626

PMA NO: PQ2532NM
SUPPLEMENT NO: 1
DATE: DECEMBER 5, 2006
REISSUED: JANUARY 7, 2010
REISSUED: NOVEMBER 17, 2011

| Article Name | Part Number | Approved Replacement for Part Number | Approval Basis and Approved Design Data | Make Eligibility | Model Eligibility |
|---|--------------|--------------------------------------|--|------------------|--|
| Bayonet, Passenger Door | 10-D6274-503 | 3916274-503 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D6274 Rev.: C Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-82 (MD-82), DC9-83 (MD-83), MD-88, MD-90-30, 717-200 |
| Inner Shaft, Handle Mechanism, Main Entry Doors | 10-N3152-3 | 65B13152-3 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-N3152 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | 757-200, 757-2200CB, 757-300 |
| Fitting-Galley Attach | 10-D2421-1 | 5952421-1 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200 |
| Fitting-Galley Attach | 10-D2421-501 | 5952421-501 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200 |
| Fitting-Galley Attach | 10-D2421-503 | 5952421-503 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200 |

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

**ALLIANCE AEROSPACE ENGINEERING, LLC.
185 PAULARINO AVE. SUITE A
COSTA MESA, CALIFORNIA 92626**

**PMA NO: PQ2532NM
SUPPLEMENT NO: 1
DATE: DECEMBER 5, 2006
REISSUED: JANUARY 7, 2010
REISSUED: NOVEMBER 17, 2011**

| Article Name | Part Number | Approved Replacement for Part Number | Approval Basis and Approved Design Data | Make Eligibility | Model Eligibility |
|---|--------------|--------------------------------------|--|------------------|---|
| Fitting-Galley Attach | 10-D2421-505 | 5952421-505 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200 |
| Fitting-Galley Attach | 10-D2421-507 | 5952421-507 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200 |
| Bar-Torsion, Flight Spoiler | 10-D4283-501 | 5954283-501 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D4283 Rev.: B Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, |
| Cam-Flight Spoiler Float | 10-D3153-505 | 3923153-505 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D3153 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, |
| Lever, Retraction Down Spring, Flight Spoiler | 10-D0944-501 | 3920944-501 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D0944 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-31, DC9-32, DC9-32F, DC9-33F, DC9-34, DC9-34F DC9-41, DC9-51, DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, |