

**FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL**

**ALLIANCE AEROSPACE ENGINEERING, LLC.  
185 PAULARINO AVE. SUITE A  
COSTA MESA, CALIFORNIA 92626**

**PMA NO: PQ2532NM  
SUPPLEMENT NO: 1  
DATE: DECEMBER 5, 2006  
REISSUED: JANUARY 7, 2010  
REISSUED: NOVEMBER 17, 2011**

Article Name	Part Number	Approved Replacement for Part Number	Approval Basis and Approved Design Data	Make Eligibility	Model Eligibility
Bushing – Flange, M.L.G.	10-V7076-531	3937076-531	Test & Computation per 14 CFR § 21.303 Drawing No.: 10-V7076 Rev.: “N/C” Date: 07/08/10 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30
Bushing – Flange, M.L.G.	10-V7076-533	3937076-533	Test & Computation per 14 CFR § 21.303 Drawing No.: 10-V7076 Rev.: “N/C” Date: 07/08/10 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30
Bushing – Flange, M.L.G.	10-V7076-535	3937076-535	Test & Computation per 14 CFR § 21.303 Drawing No.: 10-V7076 Rev.: “N/C” Date: 07/08/10 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30
BOLT	10-D4653-1	3964653-1	Test & Computation per 14 CFR § 21.303 Drawing No.: 10-D4653 Rev.: “N/C” Date: 4/8/10 or later FAA approved revisions	Boeing	DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30
Actuator Link Assy – Upper, M.L.G.	10-M7029-503	3937029-503	Test & Computation per 14 CFR § 21.303 Drawing No.: 10-M7029 Rev.: “N/C” Date: 05/25/10 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88
Actuator Link Assy – Lower, M.L.G.	10-M7030-503	3937030-503	Test & Computation per 14 CFR § 21.303 Drawing No.: 10-M7030 Rev.: “N/C” Date: 05/25/10 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88