

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

**ALLIANCE AEROSPACE ENGINEERING, LLC.
185 PAULARINO AVE. SUITE A
COSTA MESA, CALIFORNIA 92626**

**PMA NO: PQ2532NM
SUPPLEMENT NO: 1
DATE: DECEMBER 5, 2006
REISSUED: JANUARY 7, 2010
REISSUED: NOVEMBER 17, 2011**

| Article Name | Part Number | Approved Replacement for Part Number | Approval Basis and Approved Design Data | Make Eligibility | Model Eligibility |
|---|--------------|--------------------------------------|--|------------------|--|
| Bearing-Upper Shock Strut, M.L.G. | 10-A1163-1 | 161A1163-1 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-A1163 Rev.: A Date: 10/22/09 or later FAA approved revisions | Boeing | 737-600, 737-700, 737-700C, 737-800, 737-900 |
| Bearing-Sleeve, Lower Shock Strut, M.L.G. | 10-D5367-1 | 3935367-1 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D5367 Rev.: D Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30 |
| Bearing-Sleeve, Lower Shock Strut, M.L.G. | 10-D5367-501 | 3935367-501 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D5367 Rev.: D Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30 |
| Bearing-Sleeve, Lower Shock Strut, M.L.G. | 10-D5367-503 | 3935367-503 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D5367 Rev.: D Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30 |
| Bearing-Sleeve, Lower Shock Strut, M.L.G. | 10-D5367-505 | 3935367-505 | Test & Computation per 14 CFR § 21.303 Drawing No.:10-D5367 Rev.: D Date: 10/22/09 or later FAA approved revisions | Boeing | DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30 |