

**FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL**

**ALLIANCE AEROSPACE ENGINEERING, LLC.**  
**185 PAULARINO AVE. SUITE A**  
**COSTA MESA, CALIFORNIA 92626**

**PMA NO: PQ2532NM**  
**SUPPLEMENT NO: 1**  
**DATE: DECEMBER 5, 2006**  
**REISSUED: JANUARY 7, 2010**  
**REISSUED: NOVEMBER 17, 2011**

Article Name	Part Number	Approved Replacement for Part Number	Approval Basis and Approved Design Data	Make Eligibility	Model Eligibility
Bayonet, Passenger Door	10-D6274-503	3916274-503	Test & Computation per 14 CFR § 21.303 Drawing No.:10-D6274 Rev.: C Date: 10/22/09 or later FAA approved revisions	Boeing	DC9-82 (MD-82), DC9-83 (MD-83), MD-88, MD-90-30, 717-200
Inner Shaft, Handle Mechanism, Main Entry Doors	10-N3152-3	65B13152-3	Test & Computation per 14 CFR § 21.303 Drawing No.:10-N3152 Rev.: A Date: 10/22/09 or later FAA approved revisions	Boeing	757-200, 757-2200CB, 757-300
Fitting-Galley Attach	10-D2421-1	5952421-1	Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200
Fitting-Galley Attach	10-D2421-501	5952421-501	Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200
Fitting-Galley Attach	10-D2421-503	5952421-503	Test & Computation per 14 CFR § 21.303 Drawing No.:10-D2421 Rev.: A Date: 10/22/09 or later FAA approved revisions	Boeing	DC9-81 (MD-81), DC9-82 (MD-82), DC9-83 (MD-83), DC9-87 (MD-87), MD-88, MD-90-30, 717-200